


LISTADO DE PUNTOS

Nombre	Coord. X	Coord. Y	Coord. Z
73	757987.918	4066373.940	44.870
74	757947.954	4066372.715	45.270
75	757627.988	4066371.554	45.680
232	757680.842	4066373.499	44.680
233	757690.227	4066368.807	44.320
238	757682.850	4066361.978	44.850
239	757679.285	4066364.971	44.370
240	757628.184	4066364.257	45.500
242	757648.401	4066365.429	45.100
243	757646.119	4066381.250	45.100
244	757627.786	4066379.052	45.500
246	757671.070	4066357.420	44.700
247	757684.700	4066363.850	44.820
248	757693.359	4066366.525	44.750
249	757687.092	4066370.394	44.850
250	757687.490	4066380.772	44.820
251	757695.819	4066372.685	45.050
252	757697.914	4066377.172	45.040

LISTADO DE PUNTOS

Nombre	Coord. X	Coord. Y	Coord. Z
222	757553.013	4066349.893	48.320
223	757536.043	4066350.954	48.570
224	757566.723	4066367.951	48.700
225	757587.529	4066366.440	48.300
226	757557.887	4066361.050	48.650
227	757590.902	4066357.048	48.570
228	757548.812	4066355.084	48.600
229	757552.528	4066351.526	48.400
230	757569.275	4066362.571	48.640
231	757576.726	4066365.890	48.470

PLANTA GENERAL DE DISTRIBUCION DE HOJAS



BASES DE REPLANTEO

B.R.	X	Y	Z	ANAMORFOSIS
203	756622.56	4066450.06	63.740000	1.000411
2201	756682.64	4066485.57	62.180000	1.000411
202	756960.11	4066412.98	57.400000	1.000413
4504E	756858.57	4066397.29	58.760000	1.000413
201A	757105.44	4066423.06	54.800000	1.000414
201C	757367.65	4066365.41	50.100000	1.000416
201	757392.34	4066410.58	50.950000	1.000416
106	757727.38	4066392.19	43.990000	1.000418
107A	757727.69	4066349.96	44.040000	1.000418